

BDE Fails with Runtime error 217 (+ mem location)

This is generally caused by the registry entries for the Borland BDE path not matching the folder location of where the BDE files are located.

The registry entry are located HKEY_LOCAL_MACHINE\SOFTWARE then if 64bit you have to go into the Wow6432Node node.



Also



From:
https://iqxusers.co.uk/iqxhelp/ - **IQX**

Permanent link:
https://iqxusers.co.uk/iqxhelp/doku.php?id=sa27-00&rev=1379685006

Last update: **2017/11/16 21:57**